

Photo 1: View looking west from access point of site ML-014a. Commercial debris, including a trailer, have been stored on the site
(Date of Photograph 11/22/04)

Photo 2: View of access located at the eastern end of ML-014a site. Fork Ridge Road (County Route 17) can be seen in the background.
(Date of Photograph 11/22/04)

Photo 3: View looking from northern limits of ML-014a site. The town of Moundsville can be seen in the background.
(Date of Photograph 11/22/04)

Photo 4: View looking east from the western limits of the property. Commercial debris is scattered randomly throughout ML-014a site.
(Date of Photograph 11/22/04)

Photo 5: View looking south towards an adjacent hillside on ML-014a site. Erosional rills have formed on the hillside due to the absence vegetation.
(Date of Photograph 11/22/04)

Photo 6: View looking east from western limits of ML-014b site. Field vegetation covers the open areas on the site.
(Date of Photograph 11/23/04)

Photo 7: View looking north towards Moundsville from ML-014b.
(Date of Photograph 11/23/04)

Photo 8: View looking west towards prison in Moundsville from ML-014b.
(Date of Photograph 11/23/04)